HO-1034 Richard & Gladys Coon House 10671 Harding Road Private

DESCRIPTION:

The Richard & Gladys Coon House is a 1 ½-story, three-bay by three-bay frame bungalow with a CMU foundation, aluminum siding, and a gable roof with asphalt shingles and an east-west ridge. The ridge is centered over the two northern bays, with a change of pitch over the south bay. There is an interior brick chimney near the center of the building. The interior plan has three rooms in a straight line from front to back along the east side of the house, with a modern kitchen in the southeast room. There are chambers in the northwest corner and west-center portions of the house, with a stairway to the attic in the latter room. At the southwest corner is a bathroom.

SIGNIFICANCE:

William H. Coon was described in 1920 as a farmer operating a general farm, though if he only owned 10 acres, he was more likely a truck farmer like his father had been. In 1937 Coon hired surveyor J. R. Curtis to subdivide his property. It seems likely that this house was constructed around the time of the subdivision. The house is listed in the assessments and taxation records as having been built in 1934; if true, it would suggest that the house was built for a family member, and subdivision was only necessary at a later date. Indeed, after William Coon's death his widow, Mary (b. 1894), sold this house to her son, Richard L. Coon (1908-1976) in 1953. Richard Coon died in 1976, but his widow, Gladys (b. 1910), retained the house until 2004. Since Richard was 26 in 1934 and his son, John, was born in 1930, the house was probably built for him. Bungalows remained one of the most popular house types in the United States in the 1930s, so it is not surprising that the Coons chose it for Richard's young family. The house was scheduled to be demolished at the end of 2010.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

historic	Dichard & Class	lys Coon House						
757	Richard & Glad	lys Coon House						
other								
2. Location	1							
street and number	er 10671 Harding	Road					_ not for publication	n
city, town	Laurel						X vicinity	
county	Howard							
3. Owner o	f Property	(give names	and mailing a	ddresses of a	l owners)		P	
name	John & Joanna	Thompson						
street and number	er 1021 Turney A	ve.				telephone	301-503-4623	
city, town	Laurel			state MD		zip code	20707	
4. Location	of Legal D	escriptio	n					
	stry of deeds, etc.				liber	11389 folio	345	
					217		ID number	
Con	Location of	f Addition	ter District	tax parcel	211	taxi	D number	
5. Primary Con Con Dete Rec Hist Othe	Location of tributing Resource is tributing Resource is ermined Eligible for ermined Ineligible for orded by HABS/HA oric Structure Reporter:	n National Regis n Local Historic I the National Reg r the National Re ER	ter District District District Dister/Maryland	l Register	211	taxi	D number	
5. Primary Con Con Dete	Location of tributing Resource is tributing Resource is ermined Eligible for ermined Ineligible for orded by HABS/HA oric Structure Reporter:	n National Regis n Local Historic I the National Reg r the National Re ER	ter District District District Dister/Maryland Dister/Maryland Dister/Maryland Dister/Maryland	l Register	211	Resource		

7	Des	cri	nti	on
	Dea	GI I	Pu	UII

Inventory No. HO-1034

-				
Cor	10	iti	0	n
COI	Iu	ILI	v	

	excellent	deteriorated
	good	ruins
X	_fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

SUMMARY:

The Richard & Gladys Coon House is a 1 ½-story, three-bay by three-bay frame bungalow with a CMU foundation, aluminum siding, and a gable roof with asphalt shingles and an east-west ridge. The ridge is centered over the two northern bays, with a change of pitch over the south bay. There is an interior brick chimney near the center of the building. The interior plan has three rooms in a straight line from front to back along the east side of the house, with a modern kitchen in the southeast room. There are chambers in the northwest corner and west-center portions of the house, with a stairway to the attic in the latter room. At the southwest corner is a bathroom.

DESCRIPTION:

The Richard & Gladys Coon House is located at 10671 Harding Road, at the southwestern corner of the intersection with Stansfield Road, about two miles northwest of Laurel in southeastern Howard County, Maryland. The house sits at the fork in the road, facing north toward the fork. It is a 1 ½-story, three-bay by three-bay frame bungalow with a CMU foundation, aluminum siding, and a gable roof with asphalt shingles and an east-west ridge. The ridge is centered over the two northern bays, with a change of pitch over the south bay. There is an interior brick chimney near the center of the building.

The north elevation has a center door with one light over one panel, and there is a six-over-one sash in each end bay. There is a boxed cornice that follows the pitch of the rafters, and a shed-roofed dormer with three six-over-one sash. The west elevation has three six-over-one sash on the first story and one six-over-one sash in the gable end. The south elevation has a center door with one light over three lying panels, and a six-over-one sash in the west bay. The east bay has new paired sash. The east elevation has paired six-over-one sash in the south and center bays and single six-over-one sash in the north bay and gable end.

The interior plan has three rooms in a straight line from front to back along the east side of the house. The floors are carpeted and the ceilings covered with drop ceiling tiles. The architrave has a fillet backband. The front room has a wide opening on the south wall. The east-center room has a new stairway to the basement in the northeast corner and two doorways on the south. The east bay doorway leads to the southeast room, which is a modern kitchen, and the west bay doorway leads to a rear vestibule. There are chambers in the northwest corner and west-center portions of the house, with a stairway to the attic in the latter room. At the southwest corner is a bathroom. The attic contains an interconnected chamber to the north and east, and a second, small chamber to the west. Both of these chambers have 2 ½-inch pine flooring.

Inventory No. HO-1034

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet

Number 7 Page 1

Just west of the house is an open-sided shed carport structure.

8. Signific	ance			Inventory No. HO-1034
Period 1600-1699	Areas of Significance agriculture	Check and economics	justify below health/medicine	performing arts
1700-1799 1800-1899 1900-1999 2000-	archeology X architecture art commerce communications community planning conservation	education engineering entertainment/ recreation ethnic heritage exploration/ settlement	industry invention landscape architecture law literature maritime history military	philosophypolitics/government
Specific dates	N/A		Architect/Builder N/A	
Construction d	ates c. 1934			
Evaluation for:				
-	National Register		Maryland Register	Xnot evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

SIGNIFICANCE:

Shortly before his death, truck farmer Thomas Coon (1842-1911) had made an agreement with William H. Coon (1887-1950) to sell him 10 acres. William Coon was apparently known as Harry, and was a son of Thomas. Thomas Coon's son, also named Thomas, deeded the agreed-upon parcel to William in 1911. William was described in 1920 as a farmer operating a general farm, though if he only owned 10 acres, he was more likely a truck farmer like his father had been. His location, midway between Baltimore and Washington, D. C., between the Columbia turnpike and the Washington Boulevard, and near the B. & O. Railroad's Washington Branch line, would have enabled him to take advantage of two markets for his produce. In 1937 Coon hired surveyor J. R. Curtis to subdivide his property. Though many of Curtis's papers survive at the Howard County Historical Society, this plat was not among them. Nonetheless, it seems likely that this house was constructed around the time of the subdivision. The house is listed in the assessments and taxation records as having been built in 1934; if true, it would suggest that the house was built for a family member, and subdivision was only necessary at a later date. Indeed, after William Coon's death his widow, Mary (b. 1894), sold this house to her son, Richard L. Coon (1908-1976) in 1953. Richard Coon died in 1976, but his widow, Gladys (b. 1910), retained the house until 2004. Since Richard was 26 in 1934 and his son, John, was born in 1930, the house was probably built for him. Bungalows remained one of the most popular house types in the United States in the 1930s, so it is not surprising that the Coons chose it for Richard's young family. Unfortunately, the census for 1930 is not legible where Richard's occupation is recorded. The house was scheduled to be demolished in early 2011. 1

¹ U. S. Bureau of the Census, District 6, Howard County, Maryland, 1900, 1920, 1930. Howard County Genealogical Society, comp., *Howard County Maryland Records*, vol. 4 (Columbia, MD: Author, 1985), pp. 48, 58-59.

9. Major Bibliographical References

Inventory No. HO-1034

See footnotes

10. Geographical Data

Acreage of surveyed property _	.802 A		
Acreage of historical setting _	802 A		
Quadrangle name	Laurel	Quadrangle scale:	1:24000

Verbal boundary description and justification

The boundaries consist of the outlines of the property, tax map 46, parcel 217, which encompasses all of the historic buildings and features on the site.

11. Form Prepared by

name/title	Ken Short					
organization	Howard County Department of Planning & Zoning	date	October 2011			
street & number	3430 Courthouse Drive	telephone	410-313-4335			
city or town	Ellicott City	state	MD			

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Maryland Department of Planning 100 Community Place Crownsville, MD 21032-2023 410-514-7600

RICHARD & GLADYS COON HOUSE (HO-1034) 10671 HARDING ROAD

CHAIN OF TITLE

GRANTOR/HOME	GRANTEE/HOME	DATE	LIBER/ FOLIO	INSTRU- MENT	CONSIDER- ATION	ACREAGE	NOTES
Joanna L. Thompson (formerly Joanna Hopkins) / ?	John M. Thompson Joanna L. Thompson / ?	10 Oct. 2008	MDR 11389-345	Deed – fee simple	\$0	.802 A	
Gladys V. Coon / ?	Joanna L. Hopkins / ?	30 Nov. 2004	MDR - 9071-27	Deed – fee simple	\$225,000	.802 A	RLC d 5 Oct. 1976
Mary M. Coon, widow / Howard	Richard Lee & Gladys V. Coon (H/W) / ?	28 Feb. 1953	246-1	Deed – fee simple	\$5.00	.802 A	
William H. Coon	Mary M. Coon	Nov. 1935	Wills RLP 10-195	Bequest			
Thomas Coon, Administrator of Thomas Coon / Howard	William H. Coon / Howard	25 July 1911	WWLC 91-448	Deed –	?	10-0-8 ARP	Written agreement before death – died before deed made N. side of Bonas Mill Rd

DEMOLISHED 2010

HO-1034 Richard & Gladys Coon House, site 10671 Harding Road, Laurel Bing Maps Bird's Eye View, c. 2009 Looking south




Looking west



Looking north





Heavy-duty Medium-duty Light-duty Unimproved dirt ========= U. S. Route State Route



CLARKSVILLE, MD.

HO-1034 Richard & Gladys Coon House 10671 Harding Road Clarksville quad

HO-1034 Richard & Gladys Coon House 10671 Harding Road Howard County, Maryland Ken Short, photographer

Photo Log
Nikon D-70 camera
HP Premium Plus paper
HP Gray Photo print cartridge

HO-1034_2011-01-21_01 North & west elevations

HO-1034_2011-01-21_02 East elevation



40-1034 Richard & Gladys Coon House 10671 Harding Road Howard County, Maryland Ken Short 2011-01-21 MD SHPO North + west elevations 10f a





HD-1034 Richard + Gladys Coon House 10671 Harding Road Howard County, Maryland Ken Short 2011-01-21 MD SHPO East elevation 2 of 2

